



Industrial Anti-Slip Floor Signs

(for long term installation)

Features and Benefits:

- Graphic floor signs provide important hazard warning, safety information and instructional information and is an ideal communication method for the warehouse, industrial and commercial environment.
- Permanent aggressive acrylic adhesive provides industrial floor signs extended life.
- 3.5 mil premium white vinyl with 6.5 mil clear velvet embossed laminate
- Tough, anti-slip laminate provides durability and meets or exceeds industry standard for non-slip performance UL-410.
- Use on flat sealed surfaces such as painted or sealed concrete. Ensure surface is clean and dry before application.

PRODUCT DATA	VALUE	TEST METHOD	
Physical Properties			
Thickness (mils)	Base Film	3.5 +/- 10%	ASTM D 3652
	Laminate Film	6.5 +/- 10%	ASTM D 3652
	Adhesive	1.4-1.5 +/- 0.1	
	Liner	6.9 +/- 10%	
Tack (gm/sq cm)	750	ASTM D 2979	
Expected Exterior Life	Indoor use intended		
Service Temperature Range	-40°F to 176°F (-40°C to 80°C)		
Minimum Application Temperature 50°F (10°C)			
Storage Stability	Two years when stored at 70°F (21°C) and 50% relative humidity		

Disclaimer: All of the descriptive information, the typical performance data, and recommendations for the use of Stranco products shall be used only as a guide and do not reflect the specification or specification range for any particular property of the product. Furnishing such information is merely an attempt to assist you after you have indicated your contemplated use and shall in no event constitute a warranty of any kind by Stranco. All purchasers of Stranco products shall be responsible for independently determining the suitability of the material for the purpose for which it is purchased. No distributor, salesman, or representative of Stranco is authorized to give any warranty, guaranty, or make any representation in addition or contrary to the above. (6/12/20)

Industrial Floor Sign Installation Notes

FLOOR CONDITION: Floor surface must be clean prior to application of graphics. Traditional floor cleaning methods can be used to prepare the surface. Ensure that the floor surface is adequately dry before application of graphics. [CAUTION: Floor Signs can be applied at a temperature as low as 50°F (10°C).]

APPLICATION METHOD: 1. Peel the backing paper (release liner) 1" down from the top. Fold, and crease the backing paper. 2. Align and apply the graphic starting at the top using firm strokes with a plastic squeegee, stiff cardboard, or a soft cloth. Continue removing the backing paper and smooth out the squeegee. Re-squeegee the edges of the graphic using firm strokes to ensure edge adhesion.

ROUTINE MAINTENANCE: Do not clean for at least 24 hours after application. Test floor cleaning equipment to ensure suitability. Avoid damaging graphics by turning heavy equipment (e.g. fork trucks) on floor signs, or dragging pallets or other heavy items across floor signs.

CAUTION: To avoid risk of injury, immediately remove graphics if any edge of the graphic lifts, and replace with a new graphic.